



MINISTRY OF TRANSPORT AND INFRASTRUCTURE

AIR ACCIDENT INVESTIGATION DEPARTMENT

PRELIMINARY REPORT

OPERATOR:	RwandAir/Kenya Airways
AIRCRAFT TYPE :	B737-700/Embraer 190
MANUFACTURER	Boeing Company
YEAR OF MANUFACTURE:	2007
AIRCRAFT REGISTRATION:	9XR-WJ/5Y-KYT
AIRCRAFT SERIAL NUMBER:	30717
TYPE OF ENGINE:	CFM 56
DATE OF OCCURRENCE:	03 May 2013
TIME OF OCCURRENCE:	1700
LOCATION OF OCCURRENCE:	Jomo Kenyatta Int'l Airport, Nairobi, Kenya
TYPE OF FLIGHT:	Commercial
NUMBER OF PERSONS ON BOARD:	Crew - 2; Cabin crew – 4; Passengers - 55
INJURIES:	None
NATURE OF DAMAGE:	Minor
CATEGORY OF OCCURRENCE:	Incident
PIC'S FLYING EXPERIENCE:	11,900 hours

*All times given in this report is Coordinated Universal Time (UTC)
East African Local Time is UTC plus 3 hours.*



REMARKS

The Rwandair B737 aircraft had taken off from Kigali International Airport, Rwanda and landed at Jomo Kenyatta International Airport, Kenya uneventfully.

The aircraft was directed to park at Bay 15, a change from their original allocation of Bay 14. While taxiing into the designated parking bay, right hand winglet made contact with the left hand winglet of a Kenya Airways Embraer 190 aircraft parked on adjacent parking bay.

There were minor damages on both winglets of the two aircraft.

Chief Inspector
03 May 2013